



PRODUCT BULLETIN #511



SOLENOID ASSEMBLY

December 23, 2024


Dexter is discontinuing the Coil and Solenoid Assembly (054-101-00) and the Coil and Solenoid Assembly Kit (K71-755-00). The solenoid assembly itself is no longer available; therefore, the new-style integral master cylinder (released 2019) has to be used. If a solenoid and coil need to be replaced, customers must replace the entire master cylinder assembly with the complete Master Cylinder Kit (K71-757-00) which is compatible with both current and earlier models of the DX7.5L and DX8.5L surge actuators.

The K71-755-00 and 054-101-00 will remain available until inventory has been exhausted.

DISCONTINUED COIL & SOLENOID ASSEMBLY:

 054-101-00  *054-101-00 assembled on Master Cylinder	DISCONTINUED PART NUMBER	DESCRIPTION
	054-101-00	COIL AND SOLENOID ASSEMBLY
	K71-755-00	COIL AND SOLENOID ASSEMBLY KIT

REPLACEMENT MASTER CYLINDER - INTEGRAL SOLENOID, DOUBLE WIRE:

	PART NUMBER	DESCRIPTION
	K71-757-00	MASTER CYLINDER KIT - INTEGRAL SOLENOID, DOUBLE WIRE
	QTY	DESCRIPTION
	1	MASTER CYLINDER - INTEGRAL SOLENOID BODY
	1	COIL FOR SOLENOID - DOUBLE WIRE
	1	GROUND WIRE ASSEMBLY

Please contact your Dexter account manager for additional information and further assistance.

Jay Klinkerman
Product Manager